UNCLASSIFIED

AD NUMBER AD020257 **CLASSIFICATION CHANGES** TO: unclassified restricted FROM: LIMITATION CHANGES TO: Approved for public release, distribution unlimited

FROM:

Distribution authorized to DoD only; Foreign Government Information; 15 DEC 1953. Other requests shall be referred to British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.

AUTHORITY

DSTL, AVIA 18/2608, 9 Jul 2008; DSTL, AVIA 18/2608, 9 Jul 2008

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by

DOCUMENT SERVICE CENTER

KNOTT BUILDING. DAYTON 2 OHIO

RESTRICTED

The following ESPIONAGE NOTICE can be disregarded unless this document is plainly marked RESTRICTED, CONFIDENTIAL, or SECRET.

NOTICE: THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794.

THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

THE RECIPIENT IS WARNED THAT INFORMATION CONTAINED IN THIS DOCINIENT MAY BE SUBJECT TO PRIVATELY-OWNED RIGHTS.

25th Fart of Report No. AAEE/817c



MINISTRY OF SUPPLY

AEROPLANE AND ARMAMENT EXPERIMENTAL ESTABLISHMENT

BOSCOMBE DOWN

METEOR MR. 3 WF. 716 (DERGENT 8)

RADIO ACCEPTANCE TRIALS

1. THIS INFORMATION IS DISCLOSED FUR OFFICIAL USE BY THE REGITTAL COVENNIENT. ESCENSINE TO ANY OTHER GUVERNIENT THE FLEASE TO THE PINESS OF IN ANY OTHER WAY WOULD BE IN BREACH DEPARTS CONDITION. 2. THE INFORMATION SHOULD BE SAKE GUARDED UNDER RUISS ID SIGNED TO GIVE THE SAME STANDARD OF

GOVERNMENT IN THE UNITED KINGDOM.

1. THE INFORMATION CONTAINED IN THIS R

1. THE INFORMATION CONTAINED IN THIS R

1. THE INFORMATION THE PRIOR PERMISSION (
MINISTRY OF SUPPLY.

ATTENTION IS CALLED TO THE PENALTIES ATTACHING TO ANY INFRINGEMENT OF THE OFFICIAL SECRETS ACT.

THIS DOCUMENT IS THE PROPERTY OF H.M. GOVERNMENT.

It is intended for the use of the recipient only, and for communication to such officers under him as may require to be acquainted with the contents of the report in the course of their duties. The officers exercising this power of communication will be held responsible that such information is imparted with due caution and reserve.

Any person other than the authorised holder, upon obtaining possession of this document, by finding or otherwise, should forward it, together with his name and address, in a closed envelope to:—

THE SECRETARY, MINISTRY OF SUPPLY, T.P.A.3/T.1.B:, LEYSDOWN ROAD, MOTTINGHAM, S.E.9.

Letter postage need not be prepaid: other postage will be refunded.

All persons are hereby warned that the unauthorised retention or destruction of this document is an offence against the Official Secrets Acts, 1911-1939.

AEROPLANE AND ARGAMENT EXPERIMENTAL ESTABLISHMENT BOSCO. BE DOWN

(Dervent 8)

Radio Acceptance Trials

A.& A.E.E. Ref: - AAEE/411/27/Radio

M. O. S. Ref: - 44th Joint Radio Meeting, A.& A.Z.E. - M.O.S.

Period of Trials: - 2nd January, 1953 to 14th May, 1953.

Progress of issue of Report

Report No.	Title	
20th Part AADA/817e	WA.857 Brief Assessment with Restricted Air Brake Travel (Metcor Mod. 1599).	
21st - do -	WH.483 Longitudinal Manoeuvrability Characteristic in Ground Attack.	
22nd - do -	WK.648 Brief Handling Assessment with 5" H.V.A.R.	
23rd - do -	VZ.422 Hood Jettison Tests in the Blower Tunnel. VZ.473	
24th - do -	WK.648 Service Clearance Trials of Mk.8 Type 18 R.P. Installation.	

Sumary

Trials of the Rebecca Mk.7 installation were required prior to C.S.(A) clearance for Meteor Ak.8 aircraft. The trials were carried out in Meteor Mk.8 WF.716.

The installation was satisfactory in its performance and the accessibility for operating and maintenance was satisfactory.

The incorporation of modifications to the installation, suggested in paragraphs 4 and 5, would improve the layout of the installation and the visibility of the indicator during certain phases of operation.

This report is issued with the authority of

Air Commodore, Commanding A.& A.E.E.

List of Contents

		Page
1.	Introduction	3
2.	Object of trial	3
3.	Reports issued	3
4.	A.R.I.5849	3
5.	Conclusions	ر ال

List of Illustrations

	Figure
Transmitter receiver T.R.1809	1
Position of control unit type 909	2
Range and heading indicator position	3
General view of homing aerials	Į _Ļ
Transmitting acrial position	5
Omnidirectional aerial position	6

/1. Introduction.....

1. Introduction

1.1 Trials were required on Rebecca Mk.7 installation in a Meteor Mk.8 aircraft, to enable C.S.(A) clearance to be given for the installation of A.R.I. 5849. The trials were carried out in Meteor Mk.8 WF.716, fifty five hours being flown, of which three hours were by night.

2. Reports Issued

- 2.1 Already issued
- :- Nil.
- 2.2 Included in this report: A.R.I.5849.
- 2.3 Reports to follow :- Nil.

3. A.R.I. 5849

3.1 Installation Details

- 3.1.1 The T.R.X.1809 was installed in its rack, together with Junction Box Type X.2004 on the centre line of the decking of the fuselage, aft of the hatch giving access to the radio bay. This position was satisfactory for maintenance.
- 3.1.2 The transmitter aerial co-axial feeder was considered too long, and liable to be damaged by personnel working in the radio bay. (Fig. 1) The use of a 90° entry plug fitted to the feeder, would enable the cable to be laid over the top of the transmitter unit, thus reducing the feeder length.
- 3.1.3 The use of a 90° entry socket on the pilot's indicator would enable the mating of the cable on indicator plug, and would enable the indicator to be set back closer to the panel, this bringing the indicator into the pilot's field of vision when flying on instruments.
- 3.1.4 The Aerial Relay Switch Type 78A, was mounted on the starboard side of the fuselage and was satisfactory for maintenance. The aerials were incorrectly connected to this uni+ on arrival.
- 3.1.5 Power supplies for the Λ .R.I.5849 were fused by a 10 ampere fuse; this proved insufficient to deal with the starting current and was changed to a 20 ampere fuse. No trouble was experienced after the alteration of the fuses.
- 3.1.6 The Control Unit Type 909 was fitted on the starboard side of the pilot's cockpit (Fig. 2). The position was satisfactory for operation and for maintenance.
- 3.1.7 The Range and Heading Indicator was mounted on a resilient mounting on the port side of the cockpit, angled towards the pilot. (Fig. 3.) This position was satisfactory for observation, but greater ease of observation would be achieved if the indicator was moved back as far as possible in its present attitude. The use of the 90° entry socket on the connector from the Junction Box to the indicator would facilitate this alteration of indicator position, and would also be better for servicing.
- 3.1.8 The aerial system comprised housing aerials, each consisting of aerial and reflector, mounted on the port and starboard wings (Fig. 4), a transmitting aerial mounted on the centre line of the fuselage, behind the ventral tank, and an omnidirectional aerial mounted under the fuselage on the centre line, forward of the ventral tank (Figs. 5 and 6). The length of the transmitter co-axial cable was 2 ft. 6.625 inches. No frequency gap was found over the frequency band of 190-236 Mc/s with this feeder length.

3.2 Object of Trial

3.2.1 To determine the maximum range of the equipment and the

/proportional....

proportional deflections of the homing indicator.

3.3 Procedure for Trial

- 3.3.1 Range Runs. The aircraft was flown on a steady course from base, with the service selector switched on "Homing", and the range was noted when the equipment became unlocked. The selector switch was then changed to "Omni", and the aircraft continued on course, until the indicator became unlocked when the range was noted. After the range indicator became unlocked, the aircraft continued on course for a further five miles and was then turned on to a reciprocal course. The reverse sequence of operations to the outward run was then employed.
- 3.3.2 Homing Accuracy. When at the extreme range of the Rebecca Mk.7, the service selector switch was selected to the "Homing" position, and the aircraft was navigated entirely by the Heading Indicator.

3.4 Results

3.4.1 The results of the range runs were as follows:-

Altitude	Onni Range		Homing Range	
Feet	Head Aspect	Tail Aspect	Head Aspect	Tail Aspect
1,000	35	30	30	32
3,000	51	50	45	43
5,000	64	65	46	45
7,000	107	108	100	97
10,000	112	110	92	100
15,000	150	140	135	133
20,000	168	168	155	160
25,000	180	170	164	170
30,000	200	200	180	200
40,000	200	200	180	200

- 3.4.2 During the homing runs, tests were carried out at approximately 30 miles from the beacon, to determine the amount of "off course" deviation, to give half and full-scale deflection of the heading meter. The amount of "off course" for half scale deflection was approximately 6°, and for full-scale deflection approximately 16°.
- 3.4.3 During night flying the Range and Heading Indicator was difficult to read, as it was out of the area of instrument lighting.

4. Recommendations

- 4.1 The transmitter co-axial feeder should be re-routed over the top of the transmitter receiver, thus reducing the length of co-axial feeder, and a 90° entry plug substituted for the *traight entry plug fitted.
- 4.2 The straight entry plug on the junction box-indicator connector should be replaced by a 90° plug. This would facilitate servicing, and enable the indicator to be set closer to the instrument panel.
- 4.3 The power supply fuse for the equipment should be changed from 10 amperes to 20 amperes.
- 4.4 The installation was otherwise satisfactory for operation and maintenance.

5. Conclusions


5.1 Maximum range and homing accuracy of this installation are satisfactory.

/5.2....


5.2 Subject to the recommendations at para. 4 above, the installation is satisfactory for maintenance and operation.

Circulation List

D.L.R.D.a./A.L.10. 2 Copies 1 for Action A.D.R.D.L.1. 1 Copy 75 Copies R.T.O. Gloster A/c Co. 2 Copies



ļFÌG.I.



F1G.2.;




FIG.3.

A. & A.E. E. NEG. No. 15945.



FIG.4.



říĞ.5.



FIG.6



Information Centre Knowledge Services [dstl] Person Down Salishary Wils SP4-04Q 22060-6218 Tel: 01980-613753 Fax 01980-613970

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD020257

1

Date of Search: 9 July 2008

Record Summary: AVIA 18/2608

Title: Meteor Mk8 (Derwent 8): Radio Acceptance Trials

Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department) 817E 8125 Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967. The document has been released under the 30 year rule. (The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as **UNLIMITED**.